



KRAMP

Concrete Floor Paint

How to apply & maintain



1. Clean the floor

- Clean the floor thoroughly with a suitable detergent
- Sand the surface for optimal adhesion (not required)
- Wash with clean water
- Allow the floor to dry completely



2. Ensure correct room conditions

- Room temperature of 15°C or above
- Room humidity below 50%
- Floor humidity of max. 10%

Daily cleaning

Use detergent.
Do not exceed the recommended dosage.

UNTREATED CONCRETE ONLY – For previously treated concrete go to step 3



2a. Mix & stir priming paint

- Empty the bucket with Hardener into the bucket with Concrete Floor Paint
- Use the enclosed cardboard scraper to ensure that **all of the Hardener** is used
- Stir thoroughly for 3 minutes using a stirrer mounted on a drilling machine
- Add 10% water to the paint
- Mix for an additional 3 minutes



2b. Apply the priming paint

- Apply a thin layer of the priming paint with a roller, broom or brush
- Allow the floor to dry for a minimum of 4 and maximum of 24 hours
- Ensure good ventilation of the room during the drying process
- Go to step 3



3. Mix & stir paint

- Empty the bucket with Hardener into the bucket with Concrete Floor Paint
- Use the enclosed cardboard scraper to ensure that **all of the Hardener** is used
- Stir thoroughly for 3 minutes using a stirrer mounted on a drilling machine
- Do not dilute the paint



4. Apply the paint

- Apply a thin layer of the paint with a roller, broom or brush
- Allow the floor to dry for 48 hours before use
- Ensure good ventilation of the room during the drying process
- The paint is fully set after a week

NOTE: If more than one bucket is required, all buckets must have the same batch number.